Summer Intern Stream Reconnaissance Surveys 2023 Summary of Existing Conditions and Recommendations



October 2023



1317 Knopp Road, Jarrettsville, Maryland 21084

(410) 692-2164

# Summer Intern Stream Reconnaissance Surveys 2023 Summary of Existing Conditions and Recommendations

**Prepared for** 

**Quittapahilla Watershed Association** 

**Doc Fritchey Trout Unlimited** 

The Lebanon Valley Conservancy

and

Lebanon County Conservation District

Prepared by

**Clear Creeks Consulting, LLC** 

October 2023

## **Table of Contents**

Sections	Pages				
Introduction					
Methodology	1				
Protocols	1				
Field Forms and Guidance Materials	1				
Field Equipment	2				
Intern Responsibilities	2				
Summary Report and Recommendations	2				
Findings of the 2023 Field Reconnaissance Surveys	3				
General	3				
Gingrich Run	3				
Killinger Creek	13				
Snitz Creek	13				
Recommendations	48				
Final Thoughts	58				

## Introduction

A major component of the overall Quittapahilla Creek Watershed Assessment conducted between 2001 and 2003 was the Field Reconnaissance Surveys of the major tributaries to Quittapahilla Creek. The data collected during these surveys was utilized to identify problem areas and potential restoration projects in the subwatersheds. That information was summarized in the Quittapahilla Creek Watershed Restoration and Management Plan (Clear Creeks Consulting, 2006) and more recently in the Quittapahilla Creek Watershed Implementation Plan (Clear Creeks Consulting, 2021).

When the Quittapahilla Watershed Association (QWA) initiated the Summer Intern Program in 2017 the original data was sixteen years old. The Summer Intern Program involves conducting Field Reconnaissance Surveys of the subwatersheds that documents current stream reach conditions and determines the continued need for restoration/stabilization along the subwatershed stream reaches.

These surveys have been conducted by summer college interns funded by grants obtained by QWA and Doc Fritchey Chapter of Trout Unlimited and trained by Clear Creeks Consulting. The focus of the 2017 surveys was the stream reaches in the Snitz Creek subwatershed. Similar assessments were conducted during summer 2018 and 2019 along Beck Creek and Bachman Run subwatersheds, respectively. COVID prevented internships for 2020 and 2021. Funding was not available in 2022. The 2023 summer's interns initially focused on the Gingrich Run and Killinger Creek subwatersheds, but the effort was expanded to include Snitz Creek subwatershed. Funding for the 2023 Intern Program was provided by the Lebanon County Conservation District (LCCD) with grant administration provided by The Lebanon Valley Conservancy.

## Methodology

## **Protocols**

Clear Creeks Consulting developed the protocols for the surveys to provide information that can be utilized to evaluate overall riparian, channel stability, in-stream habitat and water quality conditions. The survey included:

- Characterization of existing riparian land use, channel and in-stream habitat conditions based on
- Visual observations, measurements, mapping and photo documentation of:
  - Riparian vegetation condition and stream buffer widths;
  - o Channel morphology including channel dimensions, streambed material;
  - Channel stability including streambank erosion, streambed erosion or deposition, channel blockages, and channel alterations;
  - In-Stream Habitat including percent shading, riffle embeddedness, pool quality, riffle/pool ratio, in-stream fish cover, and aquatic insect habitat;
  - Water quality including water appearance and nutrient enrichment

## Field Forms and Guidance Materials

The interns were provided with the following materials developed by Clear Creeks:

- Stream Visual Assessment Field Data Form
- Stream Visual Assessment Field Data Summary Form
- Reconnaissance Survey Field Guide Book
- Location maps (showing location of Gingrich Run, Killinger Creek and Snitz Creek relative to roads)

- Gingrich Run and Killinger Creek Property Ownership by Stream Reach with Landowner Names and Addresses
- Aerial photographs (showing Property ownership, property boundaries, Reach ID#, reach limits)
- Topographic maps (showing Reach ID#, reach limits)
- Basic Invertebrate Key for identifying stream insects and other invertebrates

## Field Equipment

The interns were provided with the following field equipment by QWA:

- 100 ft. Measuring Tape / ft./ 10ths / 100ths
- Level Rod/ ft./10ths / 100ths
- Clinometer
- Ruler, 12 inch (inches and centimeters)

## Intern Responsibilities

The interns were responsible for:

- Maintaining field equipment and field forms and additional field materials in good condition and return to Quittapahilla Watershed Association (QWA).
- Developing Snitz Creek Property Ownership by Stream Reach with Landowner Names and Addresses
- Developing Snitz Creek aerial photographs (showing Property ownership, property boundaries, Reach ID#, reach limits)
- Completing all Field Data Forms and Field Data Summary Forms for each stream reach evaluated. Mapping and photo-documenting the existing conditions along all stream reaches surveyed.
- Compiling a Report/Notebook Binder separated by stream reach that includes the completed field forms and data summary forms, maps and photographs. Appendices include the Aerials with Property/Reach Boundaries and a List of all Property Owners.
- After a QA/QC review by Clear Creeks, the Report/Notebook Binder will be submitted to the Lebanon County Conservation District (LCCD) for distribution to the Quittapahilla Watershed Association, Doc Fritchey Trout Unlimited and The Lebanon Valley Conservancy.

## Summary Report and Recommendations

To develop the following narrative, data summary tables and revised aerials Clear Creeks Consulting:

- Analyzed the data provided on the Reconnaissance Survey Data Summary Forms prepared by the interns.
- Analyzed the reach-specific photographic documentation provided by the interns.
- Analyzed the Aerial Imagery provided on the Lebanon County Tax Assessment website's Parcel Viewer.
- Analyzed the Satellite Imagery provided on Google Earth Pro.
- Measured and recorded individual stream reach lengths using the Parcel Viewer GIS tools on the Lebanon County Tax Assessment website.
- Prepared final adjustments to some reach limits and to reach-specific information in the Reconnaissance Survey Data Summary Forms based on Clear Creeks Consulting's review of the above information and discussions with the interns. Those adjustments are included in the narrative, data summary tables and revised aerials.
- Restoration recommendations were developed by Clear Creeks Consulting based on the problems identified and best professional judgment regarding the appropriate techniques for correcting those problems.

#### Findings of the 2023 Field Reconnaissance Surveys

## <u>General</u>

The land use in some of the subwatersheds has changed dramatically since the original reconnaissance surveys were conducted. Areas that were principally agricultural land with active livestock grazing or row crops have been replaced by residential subdivisions and/or commercial uses.

Riparian, channel, in-stream habitat conditions and water quality conditions vary considerably along the stream reaches surveyed. For some sections of the stream reaches, conditions have improved since the original surveys. For other sections of the stream reaches, conditions have deteriorated. Under both situations the changes appear to be directly related to the land management practices of individual property owners and their neighbors.

## Gingrich Run

The reconnaissance survey of Gingrich Run covered 49,521 linear feet (9.38 miles) of stream. The results of the survey documented that 17,799 linear feet or 35.9% of the stream is currently unstable. The unstable conditions include streambank erosion; channel incision with active head cuts; aggradation, debris jams; earthen and rubble berms along the streambanks; livestock impacts; and failing infrastructure (i.e., exposed petroleum pipelines, failed dams, failing culverts). The unstable conditions vary by reach from minor, localized erosion to widespread and severe. Table 1 below summarizes the results of the survey by stream reach and property ownership.

Reach ID	Location	Reach Length	Unstable Length	Existing Problems
		(Feet)	(Feet/%)	
Reach 1		4,534		
1A	Reiner	462	370/80	Unstable – Eroding banks ± 80% of reach; widespread bed incision with active large head cuts
1B	Weaber	1,232	120/<10	Moderately Stable – Minor, localized erosion, aggradation; few debris jams
1C	Weaber	2,840	280/<10	Moderately Stable – Minor, localized erosion, sedimentation, few debris jams; WWTP discharges into upstream end of reach.
Reach 2		5,314		
2A	Longenberger & Grumbine	423	40/<10	Moderately Stable- Minor, localized erosion, sedimentation, few debris jams
2B	Grumbine	2,385	1,789/75	Unstable – Eroding banks ± 75% of reach; widespread bed incision with active head cuts; exposed petroleum pipelines
2C	Zimmerman	1,234	1,110/90	Unstable – Eroding banks ± 90% of reach; livestock impacts
2D	Schaffer	1,272	1,018/80	Unstable – Eroding banks ± 80% of reach; channel confined by earthen and rubble berms
Reach 3		4,772		
3A	Thousand Trails	2,022	303/15	Moderately Stable – Minor, localized erosion and aggradation (15%)
3B	Thousand Trails	985	149/15	Moderately Stable – Minor, localized erosion and aggradation (15%)
3C	Thousand Trails	1,275	191/15	Moderately Stable – Minor, localized erosion and aggradation (15%); WWTP discharges into reach.
3D	Miller	490	245/50	Unstable – Incised channel with eroding banks ± 50% of reach; rip-rap 20%
Reach 4		4,061		
4A	Alger	2,411	2,170/90	Unstable – Incised channel with eroding banks ± 90% of reach; aggradation

4B	Alger	1,650	1,485/90	Unstable – Incised channel with eroding banks ± 90% of reach; aggradation
Reach 5		5,267		
5A	Sollenberger	797	638/80	Unstable – Incised channel with eroding banks ± 80% of reach; leaning and falling trees, debris jams; aggradation.
5B	Shanaman & 322 Storage	809	647/80	Unstable – Incised channel with eroding banks ± 80% of reach; leaning and falling trees, debris jams; aggradation; sink holes along reach
5C	Zimmerman & Barrett	1,746	1,397/80	Unstable – Incised channel with eroding banks ± 80% of reach; leaning and falling trees, debris jams; aggradation; sink holes along reach
5D	Lauver	1,915	1,532/80	Unstable – Incised channel with eroding banks ± 80% of reach; aggradation
Reach 6		2,221		
6A	Struphar	1,251	876/70	Unstable – Incised channel with eroding banks ± 70% of reach; aggradation; failing culvert at Louser Road
6B	Hess	970	679/70	Unstable – Incised channel with eroding banks ± 70% of reach; aggradation; failing culvert at Louser Road
Reach 7		3,452		
7A	Hess, Martin & Stahlman	1,234	987/80	Unstable – Incised channel with eroding banks ± 80% of reach; aggradation; failing culvert at Brandt Road
78	Waldhausen & Ole McDonald Estate, LLC	2,218	1,774/80	Unstable – Incised channel with eroding banks ± 80% of reach; aggradation; failing culvert at Brandt Road
	Total	49,521	17,799/35.9	



5/19/2023, 2:17:29 PM 2022 Imagery



OpenStreetMap, Microsoft, Esri, HERE, Garmin, SafeGraph, Lebanon.County



LCCGIS, Esri Community Maps Contributors, data.pa.gov; @ OpenStreetMap, Microsoft, Esri, HERE, Garmin, SafeGraph,

Lebanon County



LCCGIS, Esri Community Maps Contributors, data.pa.gov; @ OpenStreetMap, Microsoft, Esri, HERE, Garmin, SafeGraph,

Lebanon County



Lebanon County

Disclaimer: Tax maps show the approximate boundaries of taxable and non-taxable property. The property boundaries depicted should not be interpreted as the legal boundary description. The legal boundary description can be obtained from the property's deed.



![](_page_12_Figure_2.jpeg)

Lebanon County

Gingrich Run - Reach 6

![](_page_13_Figure_1.jpeg)

5/19/2023, 3:12:56 PM 2022 Imagery

![](_page_13_Figure_3.jpeg)

LCCGIS, Esri Community Maps Contributors, Dauphin County, data pa.gov, © OpenStreetMap, Microsoft, Esri, HERE, Garmin, SaleGraph,

Lebanon County

![](_page_14_Figure_1.jpeg)

5/19/2023, 3:28:22 PM 2022 Imagery

![](_page_14_Figure_3.jpeg)

LCCGIS, Esri Community Maps Contributors, Dauphin County, data pa.gov, © OpenStreetMap, Microsoft, Esri, HERE, Garmin, SaleGraph,

Lebanon County

#### Killinger Creek

The reconnaissance survey of Killinger Creek covered 34,186 linear feet (6.47 miles) of stream. The results of the survey documented that 16,219 linear feet or 47.4% of the stream is currently unstable. The unstable conditions include streambank erosion; channel incision with active head cuts; aggradation and braiding; debris jams; earthen and rubble berms, rip-rap along the streambanks; livestock impacts; and failing infrastructure (i.e., failing concrete flumes). The unstable conditions vary by reach from minor, localized erosion to widespread and severe. Table 2 below summarizes the results of the survey by stream and property ownership.

### Snitz Creek

The reconnaissance survey of Snitz Creek covered 57,127 linear feet (10.82 miles) of stream. The results of the survey documented that 30,575 linear feet or 53.5% of the stream is currently unstable. The unstable conditions include streambank erosion; channel incision with active head cuts; aggradation; debris jams; earthen and rubble berms, rip-rap, cinder block or rock walls along the streambanks; livestock impacts; dams and failing infrastructure (i.e., failing bridges and dams). The unstable conditions vary by reach from minor, localized erosion to widespread and severe. Table 3 below summarizes the results of the survey by stream and property ownership.

Reach ID	Location	Reach Length	Unstable Length	Existing Problems
		(Feet)	(Feet/%)	
Reach 1		4,783		
1A	CF Land Holdings, LLC,	3,416	683/20	Moderately Unstable – Upper section deeply incised with eroding banks throughout
	Campbelltown Vol. Fire Co. &			Middle and lower sections active floodplain along one side; five relatively long, high
	Bucks AP Sons, Inc			slopes failing ± 20% of reach; leaning and falling trees, several large debris jams
1B	Bucks AP Sons, Inc	1,367	1,094/80	Unstable – Eroding banks ± 80% of reach; channel severely trampled by livestock with
				multiple channels from cattle trails.; Banks along yard confined by earthen berms; rip-
				rap
Reach 2		4,074		
2A	Blauch, Allebach, Musser,	1,748	175/10	Moderately Stable – Minor, localized erosion (10%)
	Martin & DeCarlo			
2B	DeCarlo, Heim, Braden & Davis	1,035	1,035/100	Unstable – Moderately incised channel with eroding banks $\pm$ 100% of reach; rip-rap (10%)
2C	Bucks AP Sons, Inc	1,291	1,291/100	Unstable – Deeply incised channel with eroding banks ± 100% of reach; significant
				livestock impacts along upper section with cattle trails throughout and streambed bed
				trampled; aggradation (20%); collapsed bridge at downstream end of reach blocking
				channel
Reach 3		5.829		
ЗА	Martin	1,709	342/20	Moderately stable – Banks well vegetated; minor localized erosion ± 20% of reach;
				localized bed degradation, one active head cut
3B	Martin, Hitz & Marvel	4,120	618/15	Moderately Stable – Minor, localized erosion (10%); rip-rap (5%); collapsed bridge at top
				of reach blocking channel
Reach 4		4,380		
4A	Marvel	1,204	241/20	Moderately Unstable – Minor, localized erosion (15%); aggradation (5%); rip-rap, dams,
				water withdrawal (10%)
4B	Jobi	1,043	939/90	Unstable – Moderately incised channel with eroding banks ± 90% of reach; rip-rap (10%)

4C	Orchard View Farm, LLC, Ludwig & Eby	2,133	427/20	Moderately Unstable – Moderately incised channel with eroding banks ± 20% of reach; heavy sedimentation, rifles embedded; South Londonderry WWTP discharges into
				downstream end of reach
Reach 5		4,208		
5A	Horst & Alger (LFP) Palm City	2,451	1,961/80	Unstable – Eroding banks ± 80% of reach; rip-rap, rubble revetment and earthen berms
	Park (RFP)			along trailer park (30%); overwide channel; leaning and fallen trees, debris jams and aggradation along lower section. Pal city Park WWTP discharges into middle of reach.
5B	Alger & Ole McDonald Estate,	1,757	1,406/80	Unstable – Incised channel with eroding banks ± 80% of reach; leaning and fallen trees,
	LLC			debris jams; aggradation (50%)
Reach 6		4,034		
6A	Landmark Homes at Summer Layne, LLC & Reiff	2,109	1,476/70	Unstable – Incised channel with eroding banks $\pm$ 70% of reach; significant aggradation; rip-rap and earthen berms (5%)
6B	Landmark Homes at Pinnacle,	1,925	1,348/70	Unstable – Incised channel with eroding banks ± 70% of reach; significant aggradation;
	LLC & Snyder			rip-rap and earthen berms (5%)
Note	Huber & Burkholder	1,400	1,400/100	Unstable – Moderately incised channel with eroding banks ± 100% of reach; significant
	Properties			aggradation (80%) – 1.0 to 1.5 feet of fine silt and organic muck; livestock impacts 30%
				Restoration of these stream reaches is currently in the design and permitting phase
Reach 7		4,061		
7A	Killinger Creek Farms, LLC (Kreider) & Reiff	2,021	808/40	Moderately Unstable - Eroding banks ± 50% of reach; aggradation (30%); livestock impacts 20%
7B	Biondi, The Hershey Co. &	2,040	1,020/50	Upper Section – Moderately unstable – Eroding banks ± 20% of reach; significant
	Narrows Glen, Inc			aggradation and braiding; historic livestock impacts (50%). Lower Section – Concrete
				flume; sections failing with bank and bed erosion; sink holes
Reach 8		2,817		
8A	Narrows Glen, Inc, MFS, Inc &	1,146	NA	Concrete Flume; sections failing with bank and bed erosion; sink holes
	Rohrer			
8B	North Londonderry Township	1,671	NA	Concrete Flume; sections failing with rip-rap repairs; North Londonderry WWTP
				discharges into downstream end of reach
	Total	34,186	16,219/47.4	

Killinger Creek - Reach 1

![](_page_18_Figure_1.jpeg)

Killinger Creek - Reach 2

![](_page_19_Picture_1.jpeg)

2022 Imagery

Red: Band\_1
Green: Band\_2

0.07 0.15 0.3 km

0

LCCGIS

-

Killinger Creek - Reach 3

![](_page_20_Figure_1.jpeg)

![](_page_20_Figure_2.jpeg)

Disclaimer: Tax maps show the approximate boundaries of taxable and non-taxable property. The property boundaries depicted should not be interpreted as the legal boundary description. The legal boundary description can be obtained from the property's deed.

Lebanon County

Killinger Creek - Reach 4

![](_page_21_Figure_1.jpeg)

2022	Imagery	

Red: Band\_1

Green: Band\_2

0.07 0.15 0.3 km

0

LCCGIS

Killinger Creek - Reach 5

![](_page_22_Figure_1.jpeg)

# Killinger Creek-Reach 6

![](_page_23_Figure_1.jpeg)

# Killinger Creek-Reach 7

![](_page_24_Figure_1.jpeg)

# Killinger Creek- Reach 8

![](_page_25_Figure_1.jpeg)

Reach	Location	Reach Length	Unstable Length	Existing Problems
ID		(Feet)	(Feet/%)	
Reach 1	Elizabeth Run/Cornwall Borough	1,337	267/20	Moderately unstable - Minor, localized bank erosion; several active head cuts migrating upstream through the reach.
Reach 2	Elizabeth Run/Cornwall Borough	2,025	2,025/100	Upper Section - Unstable – Bank erosion along 60% of reach; incised due to earthen berms along banks; active head cuts at downstream end. Lower Section – Unstable – Severely eroding banks along 80% of reach. Incised to bed degradation and earthen berms along banks.
Reach 3	Elizabeth Run/Cornwall Borough	1,000	1,000/100	Unstable – Severely eroding banks along 90% of reach; aggradation 50%; exposed petroleum pipeline.
Reach 4	Elizabeth Run/Cornwall Borough			Unstable – Bank erosion along 60% of reach; stone walls failing along some banks.
4A		1,797	1,797/100	Currently in design and permitting phase
4B		1,185	1,185/100	Dropped due to landowner resistance
East Fork N	MS			
Reach 5		6,623		
5A	Cornwall Manor	4,204	420/10	Moderately stable – Minor, localized erosion 20%; few, small - moderate sized debris jams, sedimentation; one active head cut.
5B	Methodist Church Home, Hanford, Lion Secure Holdings, LLC	2,419	242/10	Stable – Minor, localized erosion 10%; riprap 10%
Reach 6	Cornwall Elementary School and Cornwall Park	669	200/30	Moderately unstable – Moderately incised with eroding banks along 30% of reach.
Reach 7	Cornwall Lebanon School District	892	401/45	Unstable – Moderately incised with eroding banks along 45% of reach length; leaning and fallen trees throughout; numerous moderate – large debris jams, lower section large trees blocking channel and causing channel diversions; Multiple, large mid-channel bars.
Reach 8		3,392		
8A	Provident National Bank Trustee for Alice Freeman	2,694	2,425/90	Unstable – Eroding banks ± 90% of reach; Incised channel due to historic bed degradation; tortuous meanders; historic livestock impacts; aggradation ups of old dam on Quinn Property.

8B	Quinn & Karinch	698	314/45	Unstable – Incised to moderately incised channel with eroding banks ± 45% of reach; Leaning and falling trees. Old concrete and timber dam at upstream end of reach. Storm flows eroding along the side-walls of dam spillway. Hole along right side of dam is leaking water. Rip-rap along spring channel.
Reach 9		2,646		
9A	Karinch, Inc, Tobias, Gristick, Chobanoff, Graby & Karinch	1,250	750/60	Moderately unstable – Incised channel with extensive bank armoring (rip-rap, cinder block and rock walls) 60% of reach length; High, unaltered banks are very unstable and eroding 30%; leaning and fallen trees common along these areas. Concrete revetment along slopes at Karinch Street Culvert is failing.
9B	Krall, Starry and Leedy	1,396	419/30	Moderately stable – Banks low, generally well vegetated, minor, localized erosion 30% of reach length; rip-rap 5%; some sedimentation.
Reach 10	Brubaker	338	135/40	Moderately stable – Banks low, generally well vegetated; Minor, localized erosion 40% of reach length; frequent, small to moderate sized debris jams, some sedimentation
West Fork	MS			
Reach 11		3,193		
11A (WF)	Hometown Alden Place, LLC	1,419	993/70	Unstable – Eroding banks ± 70% of reach; failed dam
11B (EF)	Cornwall Associates LP & Hometown Alden Place, LLC	1,774	1,242/70	Unstable – Severe bank erosion ± 70% of reach; bed incision with large active head cuts
Reach 12	Hometown Alden Place, LLC, Cornwall Associates, Northview Associates, Ebling	3,593	1,437/40	Moderately unstable – Eroding banks 40% of reach length. Leaning and fallen trees, numerous, moderate to large debris jams
Reach 13		2,531		
13A	Quentin Associates, LLC	811	243/30	Moderately stable – Low banks, generally well vegetated; minor, localized erosion affecting ±30% of reach length.
13B	Quentin Associates, LLC, Cooper, Guntle, Ganto & Garcia	1,720	1,290/75	Unstable – Moderately incised channel with eroding banks along ± 75% of reach; leaning and fallen trees, several moderate to large debris jams; stone walls along 10% of reach.
Reach 14	Vroman, Progin & Boland	525	263/50	Unstable – Moderately incised channel with eroding banks ± 50% of reach; leaning and fallen trees, debris jams; aggradation; failing bridge at ds end of reach
Reach 15	JTM & M FLP & Auman	1,907	1,431/75	Unstable – Moderately incised channel with eroding banks ± 75% of reach; rip-rap 20%
Reach 16		5,578		
16A	Perlmutter, Morrisey & Juppenlatz	1,492	970/65	Upper Section – Moderately stable – Minor, localized erosion. Lower section - Unstable – Deeply incised channel with severely eroding high banks ± 65% of total reach length; aggradation 20%

16B 16C	Reager, Szajda, Gerhart, Cornwall Professional Bldg., LLC, Snavely, Murphy, Frost, Maclean, Rights, Harpel, Scala & Anderson Anderson, Arnold, Copenhaver,	2 554	689/45	Unstable – Bank erosion along ± 45% of reach; several undercut and leaning trees; aggradation; stone walls and rip-rap 10%. Moderately unstable - Froding banks ± 30% of reach; several undercut and leaning trees;
	Bollinger, Nolt, Klink, Bollard & Schwalm	_,		aggradation 20%; rip-rap and small dams 10%
Reach 17	Gingrich, Schulte & Gebhard	2,370	1,185/50	Upper Section – Stable; Middle Section - Unstable - Eroding banks ± 50% of reach; mid- channel bars; livestock crossing; Lower Section – Unstable – Artificially low bank heights due to significant bed aggradation that increases in a downstream direction. Middle of this section are several large mid-channel bars. Downstream end of channel has filled with a large volume of sediment due backwater and flattened gradient caused by dam downstream on Stefanides Property. As a result this section has transitioned from an overwide channel into a large permanently flooded wetland system.
Reach 18	Schulte, Stefanides, GBR Leb 3, LLC, Target	1,089	1,089/100	Unstable - Eroding banks ± 100% of right bank; Upper section has significant bed aggradation 65%, resulting from the backwater and flattened gradient caused by Stefanides dam. Numerous moderate to large sized debris jams are blocking the channel on Shulte and upper Stefanides Properties. The dam failed in 2021 and has been temporarily repaired. Downstream of dam the left bank is stable.
Reach 19	Schulte, Ehrgood, Zook, Showalter, ABE Associates, North Cornwall Township & Zimmerman	2,916	2,041/70	Unstable – Eroding banks ± 70% of reach; widespread aggradation 40%. Earthen and rubble berms and rip-rap along banks; two sections of split flow with vegetated islands on Ehrgood Property. Gabion baskets installed along left bank on Schulte Property to protect new sanitary sewer. Dam with water diversion to adjacent pond on Zimmerman Property.
Reach 20	Zimmerman, Yedinak, Holland and Co. LLC, CMP Resolute, LLC, Parpagene & Cini	1,400	1,120/80	Unstable – Eroding banks ± 80% of reach; undercut banks, leaning and falling trees; overwide channel with significant aggradation 30%; dams and water withdrawal structures.
Reach 21	CMP Resolute, LLC, Weimer, Yocum, McCracken, Winslow & Villages of Creekside Homeowner Association	2,969	2,375/80	Unstable – Eroding banks ± 80% of reach; undercut banks, leaning and falling trees, several moderate sized debris jams; overwide channel with significant aggradation 30%; dams

Reach 22	Miller, Heritage Run Properties,	2,472	2,225/90	Unstable – Eroding banks ± 75% of reach; aggradation 20%; livestock impacts 25% on
	LLC, Allsop & North Cornwall			Miller Property; dam and stone walls on Allsop Property.
	Township			
Reach 23		4,680		
23A	Snyder, Harchuska, Starry,	2,084	1,250/60	Unstable – Eroding banks ± 60% of reach; aggradation; channelized. Water diversion
	Deitzler, Runnymede East			structures feed ponds on Snyder and Deitzler Properties; moderately sized debris jams
	Homeowners, Scott & Musheno			along lower section.
23B	Meadow Lane Farms Limited	1,724	1,379/80	Unstable – Eroding banks ± 80% of reach; undercut banks, leaning and fallen trees;
	(Open Space)			aggradation
23C	Dean Dairy Fluid, LLC	872	87/10	Moderately stable – Minor, localized bank erosion 10%, moderate sedimentation through
				out
	Total	57,127	31,011/54.3	

![](_page_30_Figure_1.jpeg)

7/10/2023, 9:39:37 AM		1:9,028
2022 Imagery	0 0.05	0.1 0.2 mi
Red: Band_1	0 0.07	0.15 0.3 km
Green: Band_2	LCCGIS, Esri Community OpenStreetMap, Microsoft,	Maps Contributors, data.pa.gov, © Esri, HERE, Garmin, SafeGraph,
		Lebanon County

![](_page_31_Figure_0.jpeg)

7/10/2023, 9:37:42 AM	1:9,028	
2022 Imagery	0 0.05 0.1 0.2 mi	
Red: Band_1	0 0.07 0.15 0.3 km	
Green: Band_2	LCCGIS, Esri Community Maps Contributors, data.pa.gov, OpenStreetMap, Microsoft, Esri, HERE, Garmin, SafeGra	© ph,

Lebanon County

![](_page_32_Figure_1.jpeg)

7/10/2023. 9:36:54 AM			9,028		
2022 Imagery		0	0.05	0.1	0.2 mi
Red: Band_1		0	0.07	0.15	0.3 km
Green: Band_2	LCCGIS, OpenStree	Esri etMap,	Community Microsoft,	Maps Esri,	Contributors, data.pa.gov, © HERE, Garmin, SafeGraph,
					Lebanon County

![](_page_33_Figure_1.jpeg)

Lebanon County

Snitz Creek - Reach 9

![](_page_34_Figure_1.jpeg)

7/7/2023, 10:46:38 AM	1:9,028
2022 Imagery	0 0.05 0.1 0.2 mi
Red: Band_1	0 0.07 0.15 0.3 km
Green: Band_2	LCCGIS, Esri Community Maps Contributors, data.pa.gov, © OpenStreetMap, Microsoft, Esri, HERE, Garmin, SafeGraph,

Lebanon County

![](_page_35_Picture_1.jpeg)

Red: Band\_1

0 0.07 0.15 0.3 km LCCGIS, Esri Community Maps Contributors, data.pa.gov, © OpenStreetMap, Microsoft, Esri, HERE, Garmin, SafeGraph,

Lebanon County

![](_page_36_Picture_1.jpeg)

7/7/2023, 1:27:2	5 PM				1:9,028					
2022 Imagery					0 	0.05	0.1	<del>, . , . ,</del>	0.2 	mi
Red: Band_					0	0.07	0.15		0.3 kn	n
Green: Band_	2			LCCGIS, OpenStree	Esri tMap,	Community Microsoft,	Maps Esri,	Contributor HERE, C	is, data.j Garmin,	pa.gov, © SafeGraph,
									Leb	anon County

![](_page_37_Figure_1.jpeg)

7/7/2023, 1:40:20 PM				1:9,028				
2022 Imagery				0 	0.05	0.1	0.2 mi لــــــــــــــــــــــــــــــــــــ	
Red: Band_1				0	0.07	0.15	0.3 km	
Green: Band_2			LCCGIS, OpenStree	Esri etMap,	Community Microsoft,	Maps Esri,	Contributors, data.pa.gov, © HERE, Garmin, SafeGraph,	
							Lebanon County	

![](_page_38_Picture_1.jpeg)

7/7/2023, 1:21:14 PM		1:9,028				
2022 Imagery		0	0.05	0.1	0.2 mi لــــــــــــــــــــــــــــــــــــ	
Red: Band_1		0	0.07	0.15	0.3 km	
Green: Band_2	LCCGIS, OpenStree	Esri etMap,	Community Microsoft,	Maps Esri,	Contributors, data.pa.gov, © HERE, Garmin, SafeGraph,	
					Lebanon County	

Snitz Creek - Reach 14

![](_page_39_Picture_1.jpeg)

7/7/2023, 1:20:04 PM		1:9,028				
2022 Imagery		0	0.05	0.1	0.2 mi ليب المراجع	
Red: Band_1		0	0.07	0.15	0.3 km	
Green: Band_2	LCCGIS, OpenStree	Esri tMap,	Community Microsoft,	Maps Esri,	Contributors, data.pa.gov, © HERE, Garmin, SafeGraph,	
					Lebanon County	

![](_page_40_Picture_1.jpeg)

7/7/2023, 1:18:58 PM			1:9,028					
2022 Imagery		0	0.05	0.1	0.2 mi			
Red: Band_1		0	0.07	0.15	0.3 km			
Green: Band_2	LCCGIS, OpenStree	Esri etMap,	Community Microsoft,	Maps Esri,	Contributors, data.pa.gov, © HERE, Garmin, SafeGraph,			
					Lebanon County			

Snitz Creek - Reach 16 Upper

![](_page_41_Picture_1.jpeg)

7/7/2023, 11:04:17 AM				1:9,028				
2022 Imagery				0 	0.05	0.1	0.2 mi	
Red: Band_1				o	0.07	0.15	0.3 km	
Green: Band_2			LCCGIS, OpenStre	Esri etMap,	Community Microsoft,	Maps Esri,	Contributors, data.pa.gov, © HERE, Garmin, SafeGraph,	
							Lebanon County	

## Snitz Creek - Reach 16 Lower

![](_page_42_Figure_1.jpeg)

Lebanon County

![](_page_43_Picture_1.jpeg)

7/7/2023, 11:07:47 Al 2022 Imagery Red: Band\_1 Green: Band\_2

Lebanon County

Snitz Creek - Reach 18

![](_page_44_Picture_1.jpeg)

7/7/2023,	11:10:53 AM			1:9,028						
2022 Imagery					0	0.05 ירייר	0.1		0.2 mi	É.
Red:	Band_1				0	0.07	0.15	C	.3 km	
Green:	Band_2			LCCGIS, OpenStree	Esri etMap,	Community Microsoft,	Maps Esri,	Contributors, HERE, Garn	data.pa.g nin, Sat	gov, <sup>°</sup> © feGraph,
									Lebano	on County

Snitz Creek - Reach 19

![](_page_45_Picture_1.jpeg)

Lebanon County

![](_page_46_Picture_1.jpeg)

7/7/2023, 11:19:27 AM	1:9,028
2022 Imagery	0 0.05 0.1 0.2 mi
Red: Band_1	0 0.07 0.15 0.3 km
Green: Band_2	LCCGIS, Esri Community Maps Contributors, data.pa.gov, © OpenStreetMap, Microsoft, Esri, HERE, Garmin, SafeGraph,

Lebanon County

![](_page_47_Picture_1.jpeg)

7/7/2023, 11:21:13 AM	
2022 Imagery	
Red: Band_1	
Green: Band_2	

		1:9,028											
	0	0.05	0.1		0.	2 mi							
	-			<del>, , , , , , , , , , , , , , , , , , , </del>									
	0	0.07	0.15		0.3 k	m							
LCCGIS,	Esri	Community	Maps	Contribu	tors, data	a.pa.gov,	0						
OpenStree	etMap,	Microsoft,	Esri,	HERE,	Garmin,	SafeGra	iph,						

Lebanon County

![](_page_48_Picture_1.jpeg)

Red: Band\_1

0 0.07 0.15 0.3 km LCCGIS, Esri Community Maps Contributors, data.pa.gov. © OpenStreetMap, Microsoft, Esri, HERE, Garmin, SafeGraph,

Lebanon County

Snitz Creek - Reach 23

![](_page_49_Figure_1.jpeg)

0.15 LCCGIS, Esri Community Maps Contributors, data.pa.gov, © OpenStreetMap, Microsoft, Esri, HERE, Garmin, SafeGraph, Lebanon County

0

0.07

0.3 km

Disclaimer: Tax maps show the approximate boundaries of taxable and non-taxable property. The property boundaries depicted should not be interpreted as the legal boundary description. The legal boundary description can be obtained from the property's deed.

Green: Band\_2

### Recommendations

Based on the results of the reconnaissance survey, potential restoration projects and best management practices have been identified to correct the problems documented along Gingrich Run, Killinger Creek and Snitz Creek. Some of these projects were previously identified in the Quittapahilla Creek Watershed Implementation Plan (Clear Creeks Consulting, 2021).

The restoration of Gingrich Run would include 7 projects across 15 stream reaches. The restoration of Killinger Creek would include 8 projects across 13 stream reaches. The restoration of Snitz Creek would include 20 projects across 26 stream reaches.

Tables 4, 5 and 6 below summarize the recommended restoration projects and best management practices by subwatershed, stream reach and property ownership. Unlike the tables in the Watershed Implementation Plan, no cost estimates have been included for design ad permitting or construction, given that the actual start of a specific project could be years out.

As in the WIP stream reach projects are prioritized in order of their location, that is, starting in the headwaters and working in a downstream direction. Some shorter length stream reaches have been combined into a single project if they are immediately upstream or downstream of each other. In order to improve the likelihood of obtaining funding, a general rule of thumb has been applied that limits the maximum length of a single project to less than 4,000 linear feet.

## Table 4 - Gingrich Run Prioritized Projects Summary Table

Project ID/	Location	Project/ Reach	Existing Problems	Proposed Solution
Reach ID		Length		
		(Feet)		
Project 1/	Reiner	370	Unstable – Eroding banks ± 80% of reach; widespread	Raise streambed, gradually transitioning downstream
Reach 1A			incision with active large head cuts	with boulder steps. Grade eroding banks and stabilize
				with native trees and shrubs.
Project 2/	Grumbine	1,789	Unstable – Eroding banks ± 75% of reach; widespread	Raise streambed, gradually transitioning downstream
Reach 2B			incision with active head cuts	with boulder steps. Grade eroding banks and stabilize
				with native trees and shrubs. Maintain existing buffer
				widths.
Project 2/	Zimmerman	1,110	Unstable – Eroding banks ± 90% of reach; livestock	Restore channel as a stable C4 channel and establish a
Reach 2C		2,899	impacts	minimum 15 foot riparian buffer planted with native
				trees and shrubs.
Project 3/	Schaffer	1,018	Unstable – Eroding banks ± 80% of reach; channel	Restore channel as a stable B4c channel with a
Reach 2D			confined by earthen and rubble berms	floodprone area. Replace earthen/rubble berms with
				low earthen berms setback from top of bank. Establish
				a minimum 15 foot riparian buffer with native trees
				and shrubs.
Project 4/	Miller	245	Unstable – Incised channel with eroding banks ± 50%	Leave large rip-rap undisturbed. Replace small stone
Reach 3D			of reach; rip-rap 20%	revetment with large rip-rap. Rebuild eroding banks
				with soil lifts.
Project 4/	Alger	2,170	Unstable – Incised channel with eroding banks ± 90%	Grade eroding streambanks. Establish a minimum 15
Reach 4A			of reach; aggradation	foot riparian buffer with native trees and shrubs.
Project 4/	Alger	<u>1,485</u>	Unstable – Incised channel with eroding banks ± 90%	Grade eroding streambanks. Establish a minimum 15
Reach 4B		3,900	of reach; aggradation	foot riparian buffer with native trees and shrubs.
Project 5/	Sollenberger	638	Unstable – Incised channel with eroding banks ± 80%	Remove debris jams and fallen trees. Rebuild eroding
Reach 5A			of reach; leaning and falling trees, debris jams;	banks with soil lifts. Install toe benches to narrow
			aggradation.	bankfull and baseflow channel and improve sediment
				transport.

Project 5/ Reach 5B	Shanaman & 322 Storage	647	Unstable – Incised channel with eroding banks ± 80% of reach; leaning and falling trees, debris jams; aggradation; sink holes along reach	Remove debris jams and fallen trees. Rebuild eroding banks with soil lifts. Install toe benches to narrow bankfull and baseflow channel and improve sediment transport. Investigate methods to seal sinkholes.
Reach 5C	Zimmerman & Barrett	<u>1,397</u> 2,682	of reach; leaning and falling trees, debris jams; aggradation; sink holes along reach	banks with soil lifts. Install toe benches to narrow bankfull and baseflow channel and improve sediment transport.
Project 6/ Reach 5D	Lauver	1,532	Unstable – Incised channel with eroding banks ± 80% of reach; aggradation	Remove concrete slabs revetment. Grade streambanks and plant native trees and shrubs.
Project 6/ Reach 6A	Struphar	<u>876</u> 2,408	Unstable – Incised channel with eroding banks ± 70% of reach; aggradation; culvert at Louser Road failing	Grade streambanks and plant native trees and shrubs. Establish a minimum 15 foot riparian buffer with native trees and shrubs. Notify South Annville Township regarding culvert failure.
Project 7/ Reach 6B	Hess	679	Unstable – Incised channel with eroding banks ± 70% of reach; aggradation; culvert at Louser Road failing	Grade streambanks and plant native trees and shrubs. Establish a minimum 15 foot riparian buffer with native trees and shrubs. Notify South Annville Township regarding culvert failure.
Project 7/ Reach 7A	Hess, Martin & Stahlman	987	Unstable – Incised channel with eroding banks ± 80% of reach; aggradation; culvert at Brandt Road failing	Grade streambanks and plant native trees and shrubs. Establish a minimum 15 foot riparian buffer with native trees and shrubs. Notify South Annville Township regarding culvert failure.
Project 7/ Reach 7B	Waldhausen & Ole McDonald Estate, LLC	<u>1,774</u> 3,440	Unstable – Incised channel with eroding banks ± 80% of reach; aggradation; livestock impacts; culvert at Brandt Road failing	Grade streambanks and plant native trees and shrubs. Establish a minimum 15 foot riparian buffer with native trees and shrubs. Notify South Annville Township regarding culvert failure.
	Total	16,717		

Reach ID	Location	Reach Length	Existing Problems	Proposed Solution
		(Feet)		
Project 1/	CF Land Holdings, LLC,	683	Moderately Unstable – Upper section deeply incised	Use a combination of grading for lower eroding
Reach 1A	Campbelltown Vol. Fire Co. &		with eroding banks throughout	banks and installation of bankfull benches comprised
	Bucks AP Sons, Inc		Middle and lower sections active floodplain along	of soil lifts along high eroding banks and slopes.
			one side; five relatively long, high slopes failing ±	
			20% of reach; leaning and falling trees, several large	
			debris jams	
Project 1/	Bucks AP Sons, Inc	<u>1,094</u>	Unstable – Eroding banks ± 80% of reach; channel	Remove collapsed bridge. Restore channel as a
Reach 1B		1,777	severely trampled by livestock with multiple	stable E4 channel. Fence along channel to limit
			channels from cattle trails.; Banks along yard	livestock access. Install alternative livestock water
			confined by earthen berms; rip-rap	source. Establish minimum 15 foot riparian buffer
				along both sides of stream.
Project 2/	DeCarlo, Heim, Braden &	1,035	Unstable – Eroding banks ± 100% of reach; channel	Grade streambanks and plant native trees and
Reach 2B	Davis		incision; rip-rap (10%)	shrubs. Establish a minimum 15 foot riparian buffer
				with native trees and shrubs
Project 3/	Bucks AP Sons, Inc	1,291	Unstable – Deeply incised channel with eroding	Remove failed bridges and crossings from channel.
Reach 2C			banks ± 100% of reach; significant livestock impacts	Restore channel as a stable C4 channel. Fence along
			along upper section with cattle trails throughout and	channel to limit livestock access. Install alternative
			streambed bed trampled; aggradation (20%);	livestock water source.
			collapsed bridge at downstream end of reach	
			blocking channel	
Project 4/	Marvel	241	Moderately Unstable – Minor, localized erosion	Grade streambanks and plant native trees and
Reach 4A			(15%); aggradation (5%); rip-rap, dams, water	shrubs. Establish a minimum 15 foot riparian buffer
			withdrawal (10%)	with native trees and shrubs
Project 4/	Jobi	939	Unstable – Moderately incised channel with eroding	Grade streambanks and plant native trees and
Reach 4B			banks ± 90% of reach; rip-rap (10%)	shrubs. Establish a minimum 15 foot riparian buffer
				with native trees and shrubs
Project 4/	Orchard View Farm, LLC,	427	Moderately Unstable – Moderately incised channel	Grade streambanks and plant native trees and
Reach 4C	Ludwig & Eby	1,607	with eroding banks ± 20% of reach; heavy	shrubs. Establish a minimum 15 foot riparian buffer
			sedimentation, rifles embedded; South Londonderry	with native trees and shrubs
			WWTP discharges into downstream end of reach	
1				

Project 5/	Horst & Alger (LFP)	1,961	Unstable – Eroding banks ± 80% of reach; rip-rap,	Remove debris jams. Grade eroding banks. Replace
Reach 5A	Palm City Park (RFP)		rubble revetment and earthen berms along trailer	rubble and concrete revetment with imbricated rock
			park (30%); overwide channel; leaning and fallen	walls. Narrow overwide section by installing toe
			trees, debris jams and aggradation along lower	benches.
			section. Pal city Park WWTP discharges into middle	
			of reach.	
Project 5/	Ole McDonald Estate, LLC	<u>1,406</u>	Unstable – Incised channel with eroding banks ± 80%	Grade streambanks and plant native trees and
Reach 5B		3,367	of reach; leaning and fallen trees, debris jams;	shrubs. Establish a minimum 15 foot riparian buffer
			aggradation (50%);	with native trees and shrubs
Project 6/	Landmark Homes at Summer	1,476	Unstable – Incised channel with eroding banks ± 70%	Narrow overwide sections by installing toe benches.
Reach 6A	Layne, LLC & Reiff		of reach; overwide sections, significant aggradation;	Grade streambanks and plant native trees and
			rip-rap and earthen berms (5%)	shrubs. Establish a minimum 15 foot riparian buffer
				with native trees and shrubs
Project 6/	Landmark Homes at Pinnacle,	<u>1,348</u>	Unstable – Incised channel with eroding banks ± 70%	Narrow overwide sections by installing toe benches.
Reach 6B	LLC & Snyder	2,824	of reach; overwide sections, significant aggradation;	Grade streambanks and plant native trees and
			rip-rap and earthen berms (5%)	shrubs. Establish a minimum 15 foot riparian buffer
				with native trees and shrubs
Project 7/	Killinger Creek Farms, LLC	2,021	Moderately Unstable - Eroding banks ± 50% of reach;	Restoration of these stream reaches are currently in
Reach 7A	(Kreider) & Reiff		aggradation (30%); livestock impacts 20%	the planning phase
Project 8	Huber & Burkholder	1,400	Unstable – Moderately incised channel with eroding	Restoration of these stream reaches are currently in
Note	Properties		banks ± 100% of reach; significant aggradation (80%)	the design and permitting phase
			<ul> <li>– 1.0 t0 1.5 feet of fine silt and organic muck; live</li> </ul>	
			stock impacts 30%	
	Total	15,322		

Project	Location	Reach Length	Existing Problems	Proposed Solution
ID/Reach		(Feet)		
ID				
Project 1/	Elizabeth Run/Cornwall	267	Moderately unstable - Minor, localized bank erosion;	Repaired by Borough, Dropped after 2017
Reach 1	Borough		several active head cuts migrating upstream through	Reconnaissance Survey
			the reach.	
Project 2/	Elizabeth Run/Cornwall	2,025	Upper Section - Unstable – Bank erosion along 60%	Designed and permitted; Applying for Construction
Reach 2	Borough		of reach; incised due to earthen berms along banks;	Funding 2024
			active head cuts at downstream end.	
			Lower Section – Unstable – Severely eroding banks	
			along 80% of reach. Incised to bed degradation and	
			earthen berms along banks.	
Project 3/	Elizabeth Run/Cornwall	1,000	Unstable – Severely eroding banks along 90% of	Designed and permitted; Applying for Construction
Reach 3	Borough		reach; aggradation 50%; exposed petroleum	Funding 2024
			pipeline.	
Project 4/	Elizabeth Run/Cornwall	1,797	Unstable – Bank erosion along 60% of reach; stone	Currently in design and permitting phase
Reach 4A	Borough		walls failing along some banks.	
East Fork MS	S			
Project 5/	Cornwall Elementary School	200	Moderately unstable – Moderately incised with	To avoid tree clearing, grade eroding banks along
Reach 6	and Cornwall Park		eroding banks along 30% of reach.	narrower sections with no large bank trees. Rebuild
				eroding banks with soil lifts and/or imbricated rock
				walls along wider sections with mature bank trees.
Project 5/	Cornwall Lebanon School	401	Unstable – Moderately incised with eroding banks	Remove debris jams and fallen trees. Grade eroding
Reach 7	District		along 45% of reach length; leaning and fallen trees	banks along narrower sections, rebuild eroding banks
			throughout; numerous moderate – large debris jams,	with toe wood and soil lifts along wider sections. Install
			lower section large trees blocking channel and	imbricated rock walls along outside of bends adjacent
			causing channel diversions; Multiple, large mid-	to ballfield. Establish 25 foot riparian buffer along edge
			channel bars	of ballfield.
Project 6/	Provident National Bank	2,425	Unstable – Eroding banks ± 90% of reach; Incised	Restore channel as a stable C4 channel. If future land
Reach 8A	Trustee for Alice Freeman		channel due to historic bed degradation; tortuous	use includes livestock grazing install fencing along both
			meanders; historic livestock impacts; aggradation	banks. Establish a riparian buffer a minimum of 35
			ups of old dam on Quinn Property.	feet along both banks.

Project 7/ Reach 8B	Quinn & Karinch	314	Unstable – Incised to moderately incised channel with eroding banks ± 45% of reach; Leaning and falling trees. Old concrete and timber dam at upstream end of reach. Storm flows eroding along the side-walls of dam spillway. Hole along right side of dam is leaking water. Rip-rap along spring channel.	Remove dam and repair spillway walls; grade streambanks and plant native trees and shrubs.
Project 7/ Reach 9A	Karinch, Inc, Tobias, Gristick, Chobanoff, Graby & Karinch	750	Moderately unstable – Incised channel with extensive bank armoring (rip-rap, cinder block and rock walls) 60% of reach length; High, unaltered banks are very unstable and eroding 30%; leaning and fallen trees common along these areas. Concrete revetment along slopes at Karinch Street Culvert is failing.	Stabilize eroding banks with a combination of grading along lower banks, installation of soil lifts or imbricated rock walls along higher banks. Plant native trees and shrubs along top of banks in yards.
West Fork M	S			
Project 8/ Reach 11A)	Hometown Alden Place, LLC	993	Unstable – Eroding banks ± 70% of reach; failed dam	Remove breached dam. Restore as a stable B4 and C4 channel.
Project 8/	Cornwall Associates LP &	1,242	Unstable – Severe bank erosion ± 70% of reach; bed	Restore as stable B2 step-pool channel along head
Reach 11B)	Hometown Alden Place, LLC		incision with large active head cuts	cuts. Restore lower section as a stable C4 channel.
Project 8/	Hometown Alden Place, LLC	<u>1,437</u>	Moderately unstable – Eroding banks 40% of reach	Remove leaning and undercut trees and debris jams.
Reach 12		3,672	length. Leaning and fallen trees, numerous,	Stabilize eroding banks with a combination of grading
			moderate to large debris jams	along lower banks, installation of soil lifts or
				imbricated rock walls along higher banks. Plant native
				trees and shrubs along top of banks in yards.
Project 9/	Quentin Associates, LLC,	1,290	Unstable – Moderately incised channel with eroding	Remove leaning and undercut trees and debris jams.
Reach 13B	Cooper, Guntle, Ganto &		banks along ± 75% of reach; leaning and fallen trees,	Stabilize eroding banks with a combination of grading
	Garcia		several moderate to large debris jams; stone walls	along lower banks, installation of soil lifts or
			along 10% of reach.	imbricated rock walls along higher banks. Plant native
				trees and shrubs along top of banks in yards.
Project 9/	Vroman, Progin & Boland	263	Unstable – Moderately incised channel with eroding	Remove leaning and undercut trees and debris jams.
Reach 14		1,796	banks ± 50% of reach; leaning and fallen trees, debris	Stabilize eroding banks with a combination of grading
			jams; aggradation; failing bridge at ds end of reach	along lower banks, installation of soil lifts or
				imbricated rock walls along higher banks. Remove
				failing bridge.

Project 10/ Reach 15	JTM & M FLP & Auman	1,431	Unstable – Moderately incised channel with eroding banks ± 75% of reach; rip-rap 20%	Stabilize eroding banks with a combination of grading along open grassed areas and installation of soil lifts or imbricated rock walls along wooded areas.
Project 11/ Reach 16A	Perlmutter, Morrisey & Juppenlatz	970	Upper Section – Moderately stable – Minor, localized erosion. Lower section - Unstable – Deeply incised channel with severely eroding high banks ± 65% of total reach length; aggradation 20%	Stabilize eroding banks with a combination of grading along the lower right banks, installation of toe benches with soil lifts to create a bankfull bench along the toe of the higher banks.
Project 12/ Reach 16B	Reager, Szajda, Gerhart, Cornwall Professional Bldg., LLC, Snavely, Murphy, Frost, Maclean, Rights, Harpel, Scala & Anderson	689	Unstable – Bank erosion along ±45% of reach; several undercut and leaning trees; aggradation; stone walls and rip-rap 10%.	Remove leaning and undercut trees and debris jams. Stabilize eroding banks with a combination of grading along open grassed areas, installation of soil lifts or imbricated rock walls along wooded, or tree lined areas. Plant native trees and shrubs along top of banks in yards.
Project 12/ Reach 16C	Anderson, Arnold, Copenhaver, Bollinger, Nolt, Klink, Bollard & Schwalm	<u>766</u> 1,455	Moderately unstable - Eroding banks ± 30% of reach; several undercut and leaning trees; aggradation 20%; rip-rap and small dams 10%	Remove leaning and undercut trees and debris jams. Stabilize eroding banks with a combination of grading along open grassed areas, installation of soil lifts or imbricated rock walls along wooded, or tree lined areas. Plant native trees and shrubs along top of banks in yards.
Project 13/ Reach 17	Gingrich, Schulte & Gebhard	1,185	Upper Section – Stable; Middle Section - Unstable - Eroding banks ± 50% of reach; mid-channel bars; livestock crossing; Lower Section – Unstable – Artificially low bank heights due to significant bed aggradation that increases in a downstream direction. Middle of this section are several large mid-channel bars. Downstream end of channel has filled with a large volume of sediment due backwater and flattened gradient caused by dam downstream on Stefanides Property. As a result this section has transitioned from an overwide channel into a large permanently flooded wetland system.	Upper Section - Do not disturb stable section. Middle section - Rebuild eroding banks with toe benches and soil lifts along both sides to narrow bankfull and baseflow channel. Remove mid-channel bars, utilizing bar material to construct toe benches. Lower Section - Do not disturb, maintain large wetland system.

Project 14/ Reach 18	Schulte, Stefanides, GBR Leb 3, LLC, Target	1,089	Unstable - Eroding banks ± 100% of right bank; Upper section has significant bed aggradation 65%, resulting from the backwater and flattened gradient caused by Stefanides dam. Numerous moderate to large sized debris jams are blocking the channel on Shulte and upper Stefanides Properties. The dam failed in 2021 and has been temporarily repaired. Downstream of dam the left bank is stable.	Restoration of this stream reach currently in planning phase.
Project 15/ Reach 19	Schulte, Ehrgood, Zook, Showalter, ABE Associates, North Cornwall Township & Zimmerman	2,041	Unstable – Eroding banks ± 70% of reach; widespread aggradation 40%. Earthen and rubble berms and rip-rap along banks; two sections of split flow with vegetated islands on Ehrgood Property. Gabion baskets installed along left bank on Schulte Property to protect new sanitary sewer. Dam with water diversion to adjacent pond on Zimmerman Property.	Restoration of the upper section (Ehrgood and Schulte) of this stream reach currently in planning phase. Restoration of the middle and lower sections should include removing leaning and undercut trees and debris jams;; stabilizing eroding banks by installing toe benches with soil lifts along overwide aggrading sections, grading along open grassed areas, installation of soil lifts or boulder outcrops along wooded or tree lined areas. Plant native trees and shrubs along the top of banks.
Project 16/ Reach 20	Zimmerman, Yedinak, Holland and Co. LLC, CMP Resolute, LLC, Parpagene & Cini	1,120	Unstable – Eroding banks ± 80% of reach; undercut banks, leaning and falling trees; overwide channel with significant aggradation 30%; dams and water withdrawal structures.	Restoration should include removing leaning and undercut trees and debris jams;; stabilize eroding banks by installing toe benches with soil lifts along overwide aggrading sections, grading along open grassed areas, installation of soil lifts or boulder outcrops along wooded or tree lined areas. Plant native trees and shrubs along the top of banks.
Project 17/ Reach 21	CMP Resolute, LLC, Weimer, Yocum, McCracken, Winslow & Villages of Creekside Homeowner Association	2,375	Unstable – Eroding banks ± 80% of reach; undercut banks, leaning and falling trees, several moderate sized debris jams; overwide channel with significant aggradation 30%; dams	Restoration should include installation of toe wood and soil lifts along eroding meander bends, installing toe benches with soil lifts along overwide aggrading sections, grading along open grassed areas, installation of soil lifts or boulder outcrops along wooded or tree lined areas. Plant native trees and shrubs along the top of banks.

Project 18/	Miller, Heritage Run	2,225	Unstable – Eroding banks ± 75% of reach;	Restoration should include installation of toe benches
Reach 22	Properties, LLC, Allsop &		aggradation 20%; livestock impacts 25% on Miller	with soil lifts along overwide sections to narrow the
	North Cornwall Township		Property; dam and stone walls on Allsop Property.	bankfull and baseflow channel. Installing fencing to
				limit livestock access to the channel along the Miller
				Property. Establishing a riparian buffer a minimum of
				15 feet on either side of the channel.
Project 19/	Snyder, Harchuska, Starry,	1,250	Unstable – Eroding banks ± 60% of reach;	Restoration should include remove of leaning and
23A	Deitzler, Runnymede East		aggradation; channelized. water diversion structures	fallen trees and debris jams; installation of toe wood
	Homeowners, Scott &		feed ponds on Snyder and Deitzler Properties;	and soil lifts along eroding bends; grading along open
	Musheno		moderately sized debris jams along lower section.	grassed areas. Planting native trees and shrubs along
				top of banks in yards.
Project 20/	Meadow Lane Farms Limited	1,379	Unstable – Eroding banks ± 80% of reach;	Restoration should include installation of toe wood
23B	(Open Space)		aggradation	and soil lifts along eroding bends; grading along open
				grassed areas; installation of toe benches with soil lifts
				along overwide sections to narrow the bankfull and
				baseflow channel. Planting native trees and shrubs
				along top of banks.
	Total	30,924		

### **Final Thoughts**

The results of this Summer's Reconnaissance Survey confirm that land use in the subwatersheds has changed and will continue to change as new development encroaches on forest and farmland. This is particularly the case in the Killinger Creek and Snitz Creek subwatersheds. In addition, land management practices will change with property ownership. The streams draining all of the subwatersheds have and will continue to adjust in response to these changes in land use and land management practices.

Therefore, providing reasonably current information on stream and riparian conditions throughout the subwatersheds is critical to the continuing restoration and management efforts of the Quittapahilla Watershed Association and their partners. The Summer Intern Program provides the most cost effective means of gathering that necessary information.