

Attachment 2


Existing Conditions – Quittapahilla Creek



Picture showing shallow, poor habitat section of Quittapahilla Creek downstream from Spruce Street



Picture showing steep, eroding bank in the Quittapahilla Creek downstream from Spruce Street



Picture showing low velocity, high sediment section of Quittapahilla Creek, downstream from Spruce Street.



Picture showing extended gravel bar in Quittapahilla Creek, downstream from Spruce Street